



D-protective cover




E-torque arm




Motor flange mounting dimensions

Dim	D	M	P	d	BH	BU	E	Q	The hole diameter of shaft UA										
									7.5	10	15	20	25	30	40	50	60	80	100
Motor flange	130	165	200	11	27.3	8	6	50	7.5	10	15	20	25	30	40	50	60	80	100
90B5	95	115	140	9	27.3	8	6	50	24	24	24	24	24	24	-	-	-	-	-
90B14	130	165	200	11	21.8	6	6	40	-	-	19	19	19	19	19	19	19	-	-
80B5	80	100	120	7	21.8	6	6	40	-	-	-	-	-	-	14	14	14	14	14
80B14	110	130	160	9	16.3	5	5	30	-	-	-	-	-	-	14	14	14	14	14
7B5	70	85	105	7	16.3	5	4	30	-	-	-	-	-	-	-	-	-	-	-
7B14	130	165	200	11	27.3	8	6	50	24	24	24	24	24	24	-	-	-	-	-

A-single output shaft



B-single output shaft



Output flange mounting dimensions

